

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

1/8




FIG. 1




FIG. 2

3/8




FIG. 3 A

4/8




FIG. 3 B

5/8




FIG. 4




FIG. 5

7/8

210	Event Time	message	212	Severity	215
200	01:00:00	CLIENT LOW ACTIVITY			NEW
	02:00:00	CLIENT LOW ACTIVITY			
	03:00:00	CLIENT LOW ACTIVITY			
	04:00:00	CLIENT LOW ACTIVITY			
220	05:00:00	CLIENT LOW ACTIVITY	222		
	06:00:00	DAY MODE			
230	07:00:00		232	237	239
240	08:00:00	TX STRAP TAMPER	242	VIOLATION	247
	09:00:00	TX BODY TAMPER		VIOLATION	NEW
250	10:00:00		252	257	259
260	11:00:00	NO ACTIVITY		ALARM	267
	11:05:00	NO ACTIVITY		VIOLATION	
	12:00:00	NO ACTIVITY		VIOLATION	
	13:00:00				
	14:00:00				
270	15:00:00		277		279
	16:00:00	CLIENT LOW ACTIVITY			NEW
	17:00:00	CLIENT LOW ACTIVITY			
	18:00:00				NEW
	19:00:00				
	20:00:00				
	21:00:00				
	22:00:00				
280	23:00:00		282		289
	00:00:00	NIGHT MODE			NEW
	01:00:00				
290	02:00:00		292	297	299
300	03:00:00	CLIENT HIGH ACTIVITY		PROFILE CHANGE ALARM	NEW
	03:05:00	CLIENT HIGH ACTIVITY		PROFILE CHANGE VIOLATION	307
	04:00:00	CLIENT HIGH ACTIVITY		PROFILE CHANGE VIOLATION	
	05:00:00	CLIENT HIGH ACTIVITY		PROFILE CHANGE VIOLATION	
	06:00:00	CLIENT HIGH ACTIVITY		PROFILE CHANGE VIOLATION	
	07:00:00	CLIENT HIGH ACTIVITY		PROFILE CHANGE VIOLATION	
	08:00:00				
	09:00:00				

FIG. 6




FIG. 7